Real results.





Courtesy of J. Dover, ME





Courtesy of S. Chilukuri, M.





Courtesy of J. Dover, MD

To view more real results, visit

ThreeForMe.com

As easy as one, two, ThreeForMe.

Say goodbye to tired, dull skin—and hello to a brighter, younger-looking you.

To find out more, visit

ThreeForMe.com

(V N O V R E

©2016 Cynosure, Inc. Cynosure is a registered trademark. Icon and ThreeForMe are trademarks of Cynosure, Inc.

Reduce wrinkles, sun damage & facial veins



A brighter solution

for dull skin

921-2500-002 Rev.2 12/2016

TREATMENT

Why solve one skin problem when you can solve three?

The ThreeForMe laser treatment is the proven way to get rid of fine lines, wrinkles, age spots, sun damage and unsightly veins, all at the same time.

It's Safe.

Gentle, non-invasive laser procedure

It's Quick.

30-minute treatment

It's Convenient.

Minimal downtime

You'll be amazed at how much younger you can look and feel with ThreeForMe.

It's right for you.



How do ThreeForMe treatments work?

The ThreeForMe treatment is exclusive to the clinically proven Icon™ laser. The procedure is performed in two steps, or "passes":

The **first pass** treats discoloration and facial vessels using a technology called Intense Pulsed Light, or IPL. IPL addresses sun damage including freckles, brown spots or age spots, and unsightly veins including broken blood vessels, facial veins and rosacea.

The **second pass** uses Icon's "microbeam" laser technology that gently renews the skin by generating collagen and elastin—keys to the support structure of our skin. This results in the improvement of fine lines, wrinkles, scars and other surface imperfections.

How will it feel?

During ThreeForMe treatments most people feel only minimal discomfort. After the treatment, you may experience some minor redness and swelling similar to a mild sunburn.

Ask your doctor about

three for me



Undo wrinkles, sun damage and facial veins.

Only ThreeForMe treatments address all these conditions in one procedure. A typical course of treatment involves one to three procedures at one-month intervals. Your doctor will recommend a treatment plan that's right for you.

When will I see results?

You will see continuing improvement in the skin's appearance during and after a course of treatment, with visible results after each treatment. Brown spots should go away in one to three weeks. Overall results should improve progressively over six months as your skin naturally responds to the treatment.

